

ANEXO III - Principais marcas e modelos dos equipamentos

Campus	Marcas/modelos
	Equipamentos de Processamentos de dados: Microcomputadores, Computadores portáteis (Notebook) e Servidores
AL	Dell OptiPlex 755, 780, 790, 990, 3070, 3080, 3090, 7010, 7040 e 7070; HP ProDesk 600 G1, Compaq 6005 Pro e EliteDesk 800; Servidores Dell, IBM System x3550 e Supermicro X8DTU; Notebooks HP 450, Lenovo ThinkPad E14 Gen 3 e ThinkPad X240, Asus 1005HA e Datem DCM3A-4; entre outros.
FW	Servidor HP DL380e-Gen8, servidor HP DL360p-Gen 8, servidor IBM x3550 M3, notebook Daten, notebook Sansung, notebook Lenovo, Dell Desktop, HP Desktop, Lenovo Desktop, Arquimedes Desktop, entre outros.
JA	DELL PowerEdge R740xd, Dell Desktop, HP Desktop, Daten, Arquimedes Desktop
JC	Dell Optiplex 790, HP Compaq 6005 Pro, Servidor Dell R720
PB	Desktop - Dell Optiplex 7010, 9010, HP Prodesk, HP Elitedesk 800. Servidor Dell R630, Dell R740XD, Supermicro. Notebook HP.
RT	Dell OptiPlex 780, 790, 990, 3070, 3080, 3090, 7010, 7040, 7050 e 7070; HP ProDesk 600 G1, Compaq 6000 Pro, Compaq 6005 Pro, Arquimedes Desktop, Daten Desktop, notebook Daten, notebook Sansung, notebook Lenovo, notebook HP, notebook DELL, Servidor CISCO.
SR	Desktop - Dell Optiplex 7010, 9010, HP Prodesk, HP Elitedesk 800. Servidor Dell R630, Dell R740XD, Supermicro. Notebook HP.
SAN	Desktop - Dell Optiplex 7010, 9010, HP Prodesk, HP Elitedesk 800. Servidor Dell R630, Dell R740XD, Supermicro. Notebook HP.
SAU	Dell OptiPlex 790, 990, 3070, 3080 e 7050; HP ProDesk , Servidores Dell r720, Notebooks HP 450, Lenovo ThinkPad E14 Gen 3 e ThinkPad X240, entre outros.
SB	PCs Dell Optiplex 9010, 7040,790, 3080;
SVS	Dell OptiPlex 780, 790, 990, 3070, 3080, 3090, 7010, 7040 e 7070; HP ProDesk 600 G1, Compaq 6005 Pro e EliteDesk 800; Servidores Dell R720 e R730, IBM System x3550 e Supermicro X8DTU; Notebooks HP 450, Lenovo ThinkPad E14 Gen 3 e ThinkPad X240, Asus 1005HA e Datem DCM3A-4; entre outros.
URU	Dell OptiPlex 780, 790, 990, 3070, 3080, 3090, 7010, 7040 e 7070; HP ProDesk 600 G1; Servidores Dell R720; Notebooks Dell e HP; entre outros.
	Ativos de redes (Switch, Roteador, equipamentos correlatos)
AL	Controladora Cisco 2504; Acess Point Cisco Aironet; Switch Dell, Switch HP, Switch TP-link, Switch Cisco,
FW	Mikrotik CCR-1036, Switch Dlink DGS-1510-28, Switch SMC 8150L2, Switch HP V1095-48, Switch Dlink DGS-1500-52, Switch Dlink DGS-1510-28, Switch Intelbras SG 2404 MR, Unifi UAP Pro, UnifiUAP-AC-Pro, Cisco Aironet 1600, Cisco Aironet 1830 mobility express.
JA	Controladora Cisco 2504; Acess Point Cisco Aironet; Switch Dell, Switch HP, Switch TP-link
JC	Switch HP 1910. Controladora Cisco 2504. Acess Point Cisco Aironet.
PB	Switch HP 1910, 1920, 5120, 5130, Huawei S5720, Mikrotik CRS328. Controladora Cisco 2504. Acess Point Cisco Aironet.
RT	Controladora Cisco 2504, Acess Point Cisco AIRCAP1702, Switch Catalyst 2960, SG300.
SR	Switch HP 1910, 1920, 5120, 5130, Huawei S5720, Mikrotik CRS328. Controladora Cisco 2504. Acess Point Cisco Aironet.
SAN	Switch HP 1910, 1920, 5120, 5130, Huawei S5720, Mikrotik CRS328. Controladora Cisco 2504. Acess Point Cisco Aironet.
SAU	Switch HP 1910, 1920, 5120, 5130, Controladora Cisco 2504. Acess Point Cisco Aironet.
SB	AP Cisco Air cap 1702LZK9; Storage Dell EqualLogic PS6110
SVS	HP 1920-24G; HPE OfficeConnect Switch 1920S; HP-v1910; D-Link DGS-1510-28; HP-A5120; DLINK-3028; Cisco SGE2000; DLINK-DES3028; HP A5120; 3COM-4500; Planet SGS-5240; HP A5500-EL; DELL N3024; DELL N4032; DELL EMC S4148F-ON; Roteador/Firewall Dell SonicWall NSA4600; Storage Dell XT380 e Equallogic PS6210; Controladora Cisco 5508; Access Points Cisco Aironet; entre outros.
URU	Switchs HP, Intelbras, entre outros. Controladora Cisco 2504. Acess Point Cisco Aironet.
	Impressoras e multifuncionais
AL	Samsung ML-2851, HP LaserJet P2035N, HP LaserJet Pro 400
FW	HP LaserJet P2015, HP LaserJet P2035n, Oki B431dn+, Sansung SL-M3375FD, Epson L6270 Series.
JA	Multifuncional HP LaserJet Pro M1212nf ; Epson EcoTank L375; Samsung SL-M4075FR
JC	Samsung ML-2851, HP LaserJet P4014N, HP CM2320NF, HP LaserJet M551

PB	Datacard SP35 Plus, HP Laserjet
SR	LexMark e360; Xerox Phaser
SAN	HP LaserJet 500 color M551
SAU	HP LaserJet 1100
SVS	HP M277, M401, M551, M1132, 3525, CP 2025, 2055, CP 2020; Xerox 3125; Samsung ML-2851; Brother DCP-L5652DN, DCP-6902DW; entre outros.
	Monitores de vídeo e scanner
AL	AOC, Dell, HP, Lenovo, LG, Samsung; entre outros.
FW	Dell, LG, HP, Lenovo, Samsung; entre outros.
JA	DELL, HP, Scanner Avison
JC	Dell, LG, AOC, HP, Daten
PB	LG, DELL, HP, AOC, Samsung; entre outros.
RT	AOC, Dell, HP, LG, DATEN.
SR	Dell, LG, AOC, Samsung, HP
SAN	Dell, AOC, LG, HP, Samsung
SAU	Dell, AOC, LG, HP, Samsung
SVS	LG, DELL, HP, AOC, Samsung; entre outros.
URU	LG, DELL, HP, AOC, Samsung; entre outros.